


Miscellaneous



This washer hose failed, causing significant flood damage to a house.



Culp & Tanner, by using our natural “investigative nature”, found that the manufacturer had problems with their jig, which left a cut in the hose wall and a slight bubbling at the connection of the hose to the screw cap. This manufacturing defect led to the failure of the hose.