

ORIGIN and CAUSE - Settlement



This homeowner reported that his front masonry support piers were leaning.



Not only were they leaning, but they had settled so far that they were no longer supporting the roof beam.



The cracks in the soils are a classical sign of clay soils, which shrink significantly when they dry out. The soils shrinkage cause the piers to settle and lean.

INVESTIGATIVE ENGINEERING SERVICES

Culp and Tanner, Inc.
Structural Engineers

55 Independence Circle, Suite 201
Chico, CA 95973
Phone: (530) 895-3518