

ORIGIN and CAUSE - Concrete Cracks



The homeowner of this driveway claimed heavy road construction equipment from a nearby road extension project used his driveway as a place to turn around, cracking his driveway.

Side yard fences separated the backyard from the front of the house.



Since the backyard patio slab exhibited the same cracking as the front driveway, it was perplexing how the construction equipment got to the backyard patio without damaging the lawn or fences! Obviously the claim was denied.

INVESTIGATIVE ENGINEERING SERVICES

Culp and Tanner, Inc.
Structural Engineers

55 Independence Circle, Suite 201
Chico, CA 95973
Phone: (530) 895-3518